


Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	Sh A
PC100045	120	100	60	40	60	-	M12i	11	14	45°
PC100055	120	100	60	40	60	-	M12i	11	14	55°
PC100065	120	100	60	40	60	-	M12i	11	14	65°
PC100075	120	100	60	40	60	-	M12i	11	14	75°
4.M12x100VERZ	Height adjustable spindle M12 x 100 complete									

L = length
Ls = spacing mounting holes
K = diameter lid
D = diameter
H = height
B = width
M = screw thread
d1 = bore diameter width
d2 = bore diameter length
d3 = bore diameter length
 Shore A = hardness



Load Fz



Ratio horizontal stiffness
 Cx (longitudinal) and Cy
 (transverse direction) compared
 to Cz (load direction)
 Cz : Cx : Cy
 1 : 2,5 : 0,75

